

# Jamb/Sub Jamb attachment located between Ridge Purlins at Peak

SHT. NO. **AC00917**  
DATE **Jul '11** REV. NO. **00**

Notes:

- 1.) See EF09104 for Endwall Column attachment when located at same Purlin space as Jamb/Sub Jamb.
- 2.) Purlins extends past Bridge Channel flange when "Optional" Overhang or Facade is required at endwall.

