

# Endwall Column attachment located between Ridge Purlins at Peak

SHT. NO. EF09104

DATE Dec '12 REV. NO. 01

Notes;

- 1.) See AC00917 / AC00921 for Jamb/Support Column attachment when located at same Purlin space as Endwall Column.
- 2.) Purlins extend past Bridge Channel flange when "Optional" Overhang or Facade is required at endwall.

