



Note: Field Cutting Light Transmitting Panels

Light transmitting panels may need to be cut in the field.

If required, follow these steps:

- Up to five (5) LTP's may be cut at one time.
- A circular saw with a 24 tooth per inch blade, will work best.
- Cut slow and allow the blade to work without excess pressure.
- Allow the blade to cool between cuts.